NUCLEAR REGULATORY COMMISSION REGION III

799 HOUSEVELT HOAD GLEN ELLYN, ILLINOIS 60127

MAY 5 2 1 2

Docket No. 50-341

The Detroit Edison Company
ATTN: W. S. Orser
Senior Vice President
Nuclear Generation
6400 North Dixie Highway
Newport, MI 18.56

Dear Mr. Orser:

This refers to the inspection conducted by S. Stasek, K. Riemer, T. Tongue, M. Peck, and D. Roth of this office on March 12 to May 7, 1992. The inspection included a review of authorized activities for your Fermi 2 facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements. However, as described in the enclosed inspection report, the violation was categorized at Severity Level V and is not being cited because the criteria specified in VII.B.1 of the "General Statement of Policy and Procedures for NRC Enforcement Actions," (Enforcement Policy, 10 CFR Part 2, Appendix C (1992)), were satisfied.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

M. P. Phillips, Chief

Reactor Projects Section 28

Enclosure: Inspection Report No. 50-341/92007(DRP)

See Attached Distribution

1601

MAY 2 2 1992 Docket No. 50-341 The Detroit Edison Company ATTN: V. S. Orser Senior Vice President Nuclear Generation 6400 North Lixie Highway Newport, MI 48166 Dear Mr. Orser: This refers to the inspection conducted by S. Stasek, K. Riemer, T. Tongue, M. Peck, and D. Roth of this office on March 12 to May 7, 1992. The inspection included a review of authorized activities for your Fermi 2 facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report. Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel. During this inspection, certain of your activities appeared to be in violation of NRC requirements. However, as described in the enclosed inspection report, the violation was categorized at Severity Level V and is not being cited because the criteria specified in VII.B.1 of the "General Statement of Policy and Procedures for NRC Enforcement Actions," (Enforcement Policy, 10 CFR Part 2, Appondix C (1992)), were satisfied. In accordance with 10 CTR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Doc ment Room. We will gladly discuss any questions you have concerning this inspection. Sincerely, M. P. Phillips, Chief Reactor Projects Section 2B Enclosure: Inspection Report No. 50-341/92007(DRP) See Attached Distribution RIII Tongue/dp

Distribution:

cc w/enclosure: D. R. Gipson, Assistant Vice President & Manager Nuclear Production John Tibai, Supervisor of Compliance P. A. Marquardt, Corporate Legal Department DCD/DCB (RIDS) OC/LFDCB Resideri Inspector, RIII James R. Padgett, Michigan Public Service Commission Harry H. Voight, Esq. Michigan Department of Public Health Monroe County Office of Civil Preparedness Fermi, LPM, NRR