

yellow

FEB 11 1985

Alabama Power Company
ATTN: Mr. R. P. McDonald
Senior Vice President-Nuclear Generation
P. O. Box 2641
Birmingham, AL 35291

Gentlemen:

SUBJECT: REPORT NOS. 50-348/85-04 AND 50-364/85-04

On January 14 - 17, 1985, NRC inspected activities authorized by NRC License Nos. NPF-2 and NPF-8 for your Farley facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

The inspection findings indicate that certain activities violated NRC requirements. The violation, references to pertinent requirements, and elements to be included in your response are presented in the enclosed Notice of Violation.

Should you have any questions concerning this letter, please contact us.

Sincerely,

David M. Verrelli, Chief
Reactor Projects Branch 1
Division of Reactor Projects

Enclosures:

- 1. Notice of Violation
- 2. Inspection Report
Nos. 50-348/85-04
and 50-364/85-04

cc w/encls:

- W. O. Whitt, Executive Vice President
- J. D. Woodard, Plant Manager
- W. G. Hairston, III, Manager,
Nuclear Engineering
and Technical Support
- J. W. McGowan, Manager-Safety Audit
and Engineering Review
- H. O. Thrash, Manager, Nuclear
Operations
and Administration
- W. G. Ware, Supervisor-Safety Audit
and Engineering Review

bcc: (See page 2)

8503070110 850211
PDR ADOCK 05000348
Q PDR

IE-01
11

Alabama Power Company

2

FEB 11 1985

bcc w/encls:
Document Control Desk
State of Alabama
NRC Resident Inspector
E. Reeves, Project Manager, NRR

RII

JM
JMathis:es
2/6/85

RII

FJ
FJape
2/6/85

RII

AR
ARHerdt
2/21/85