

ENCLOSURE 1

NOTICE OF VIOLATION

Florida Power and Light Company  
Turkey Point

Docket Nos. 50-250 and 50-251  
License Nos. DPR-31 and DPR-41

The following violations were identified during an inspection conducted on December 17-21, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 6.8.1 requires that written procedures and administrative policies be established, implemented and maintained that meet or exceed the requirements and recommendations of Appendix A of Regulatory Guide 1.33. Regulatory Guide 1.33 recommends that the licensee have radiation protection procedures. Health Physics procedure HP-12, Operation of the ND 6650 GeLi Spectrometer, step 8.6.2, requires that a daily energy calibration be performed on the GeLi.

Contrary to the above, on October 13-14, 1984, a daily energy calibration was not performed for the GeLi Spectrometer and the instrument was used to analyze six air samples.

This is a Severity Level V violation (Supplement IV).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: JAN 23 1985

8503070227 850123  
PDR ADOCK 05000250  
G PDR