

Entergy Operations, Inc.

P.O. Exis. B Resta, LA 70060 Tel 504 539 6774

R. F. Burski

Dispotor Nacional Galley Automobier II

W3F1-92-0184 A4.05 QA

July 30, 1992

U.S. Nuclear Regulatory Commission ATTN: Doct ment Control Desk Washington, D.C. 20555

Subject:

Waterford 3 SES Docket No. 50-382 License No. NPF-38

Waterford 3 Organization Change

#### Gentlemen:

Entergy Operations, Inc. has recently restructured the Waterford 3 site organization. This has necessitated a change to the Waterford 3 SES Emergency Plan.

Pursuant to 10CFR50. Appendix E, Section V, we are herewith informing you of the resulting changes that will be required to the Emergency Plan. These changes do not decrease the effectiveness of the Emergency Plan based on a 10CFR50.54(q) review.

Attached is a marked-up copy of pages 5-1 and A-5-1A of the Emergency Plan indicating the changes which will be required.

The changes will be incorporated into the next revision of the Emergency Plan will as scheduled for issuance during the fourth quarter of 1992.

Should you have any questions, please contact T.W. Gates at (504) 739-6697.

Very truly yours,

RFB/TWG/ssf Attachments

001

R.D. Martin (NRC Region IV ), D.B. Spitzberg ,NRC Region IV),

D.L. Wigginton (NRC-NRR), R.B. McGehee, N.S. Reynolds,

NRC Resident Inspectors Office

100007 9208030104 920730 PDR ADDCK 05000382

chhair IR RAB

A045/

#### WATERFORD 3 SES EMERGENCY PLAN

# 5.0 ORGANIZATIONAL CONTROL OF EMERGENCIES

Of paramount importance in response to any emergency situation is a coordinated management approach providing technical and logistical direction to mitigate the consequences of an accident.

The LP&L and Waterford 3 organizational structures are based on staffing the Emergency Facilities, discussed in Section 7.0, to respond to actions in three critical areas:

- o Plant Control
- o Site Response
- O Nearsite/Offsite Pesponse

The responsibilities associated with each Emergency Organization position are defined in this section.

The initial selection of personnel assigned emergency responsibilities is based, as much as possible, or the normal Waterford 3 organization. These are the personnel most knowledgeable of plant systems, personnel and their interrelationships. The initial selection is followed by specific training in the assigned areas of configuration management as required by Section 8.0 of this document.

# 5.1 Waterford 3 Organizations

### 5 1.. Normal Organizations

This section provides a brief description of the normal Waterford 3 Organization, as shown in figure 5-lA. A more detailed description is contained in FSAR Section 13.1.1 and 13.1.2. The Waterford 3 organization is headed by the Vice President, Operations, Waterford 3.

### 5.1.1.1 Normal Plant Organization

The Plant Organization includes the personnel encompassing both the management and operating groups. The management and technical engineering groups are onsite during normal work hours daily Monday through Friday, holidays excluded. Plant Operations, Maintenance, Chemistry, Health Physics, and Security personnel are onsite on a 24-hour basis, holidays included. The Plant Organization is responsible for the day-to-day operation and maintenance associated with the Waterford 3 SES. The Plant Organization is headed by the General Manager Plant Operations who reports to the Vice President, Operations, Waterford 3.

#### 5.1.1.2 Operations Plant Support Groups

The Operations Support & Accomments,
Engineering, Plant Modification & Construction,
Site Support and Nuclear Safety Groups provide
support to the Plant Organization and report to
the Vice President, Operations, Waterford 3.

# W3 FES EMERGENCY PLAN FIGURE 5-1A

ENTERGY OPERATIONS, INC. WATERFORD 3 ORGANIZATION

