

LICENSEE EVENT REPORT

EXHIBIT A

ATTACHMENT

LER NO. 50-368/80-045/04X-3

Cause Description and Corrective Action (Continued)

| observed since the completion of the modification.



ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

February 25, 1985

2CAN028508


U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Licensee Event Report
No. 80-045/04X-3

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Environmental Technical Specification 4.6.2.b, attached is the subject report concerning the inoperability of the condenser off-gas radiation monitor 2RE-0645. This is an update to a previous submittal dated December 2, 1980.

Very truly yours,


J. Ted Enos
Manager, Licensing

JTE:RJS:ds

Attachment

cc: Mr. Richard C. DeYoung
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Norman M. Haller, Director
Office of Management & Program Analysis
U. S. Nuclear Regulatory Commission
Washington, DC 20555

LEZ3
1/1