10CFR50.71(e)(4) PHILADELPHIA ELECTRIC COMPANY NUCLEAR GROUP HEADQUARTERS 955-65 CHESTERBROOK BLVD. WAYNE, PA 19087-5691 July 21, 1992 (215) 640-6000 Docket Nos. 50-352 50-353 License Nos. NPF-39 NPF-85 U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555 SUBJECT: Limerick Generating Station, Units 1 and 2 Updated Final Safety Analysis Report Revision 2 Revised Page Replacement Instructions Dear Sirs: On June 30, 1992, we provided one original and ten copies of Revision 2 of the Updated Final Safety Analysis Report (UFSAR) for Limerick Generating Station (LGS), Units 1 and 2. UFSAR Revision 2 was provided on a page replacement basis with a list of effective pages identifying the latest revision date of all current pages. effective pages, we provided page replacement instructions for incorporating Revision 2 into the NRC copies of the LGS UFSAR. Subsequent to the June 30, 1992 transmittal, we identified several errors in the page replacement instructions, which we wish to correct. The following text pages should not have been listed on the page replacement instructions, since they are not part of Revision 2. 2.1-55 2.1-63 2.1-59 2.1-65 2.1-61 4.2-3 If you have any questions or require further information, please contact us. Very truly yours, G. J. Beck, Manager Licensing Section Nuclear Services Department T. T. Martin, Administrator, Region I, USNRC T. J. Kanny, USNRC Senior Resident Inspector, LGS 08030205 920 R ADGCK 050