

JUL 22 1992

Docket Nos. 50-317  
50-318

Mr. George C. Creel  
Vice President - Nuclear Energy  
Baltimore Gas and Electric Company  
Calvert Cliffs Nuclear Power Plant  
MD Rts 2 and 4, Post Office Box 1535  
Lusby, Maryland 20657

Dear Mr. Creel:

Subject: COMBINED INSPECTION NOS. 50-317/92-17; 50-318/92-17

This refers to the safety inspection conducted by Mr. J. Furia of this office on July 13-17, 1992, of activities authorized by NRC License Nos. DPR-53 and DPR-69, and to the discussion of our findings held by Mr. J. Furia with Mr. P. Katz and other members of your staff at the conclusion of the inspection.

Areas examined during this inspection are important to health and safety and included the radiation protection program, as described in the NRC Region I Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Your radiation protection program continues to be aggressive in controlling work activities, especially during the Unit 1 refueling outage. However, your outage work planning has been less than successful, resulting in total site dose for the outage being significantly higher than originally projected. Due to the outage scope, especially the number of plant modifications done during the outage, the length of the outage has been considerably greater than that which was planned for. In addition, the failure to freeze work scope prior to the outage, together with the lack of an appropriate outage work plan, has led to the total dose for the outage to be significantly above the outage goal. It is our understanding that your staff has also identified these concerns and plans to take corrective action prior to the Unit 2 refueling outage in 1993. No safety concerns or violations of regulatory requirements were identified.

9208040005 920722  
PDR ADOCK 05000317  
G PDR

OFFICIAL RECORD COPY

Baltimore Gas and  
Electric Company

2

Your cooperation with us in this matter is appreciated.

Sincerely,

Original Signed by  
James H. Joyner

James H. Joyner, Chief  
Facilities Radiological Safety and Safeguards Branch  
Division of Radiation Safety and Safeguards

Enclosure: NRC Region I Combined Inspection Report Nos. 50-317/92-17; 50-318/92-17

cc w/encls:

G. Detter, Director, Nuclear Regulatory Matters (CCNPP)  
R. McLean, Administrator, Nuclear Evaluation  
J. Walter, Engineering Division, Public Service Commission of Maryland  
K. Burger, Esquire, Maryland People's Counsel  
R. Ochs, Maryland Safe Energy Coalition  
K. Abraham, PAO (2)  
Public Document Room (PDR)  
Local Public Document Room (LPDR)  
Nuclear Safety Information Center (NSIC)  
NRC Resident Inspector  
State of Maryland (2)

OFFICIAL RECORD COPY

IE 00

Baltimore Gas and  
Electric Company

3

bcc w/encls:

Region I Docket Room (with concurrences)

W. Lanning, DRS

J. Joyner, DRSS

C. Cowgill, DRP

J. Yerokun, DRP

L. Nicholson, DRP

S. Greenlee, DRP

P. Wilson, SRI - Calvert Cliffs

D. McDonald, NRR

R. Lobel, OEDO

R. Capra, NRR

DRS SALP Coordinator

DRSS SALP Coordinator

D. Holody, EO

RI:DRSS



J. Furia

7/24/92

RI:DRSS



W. Pasciak

7/24/92

RI:DRSS



J. Joyner

7/24/92

OFFICIAL RECORD COPY

IE 06