

RIVER BEND STATION

POST OFFICE BOX 220

ST FRANCISVILLE. LOUISIANA 70775

346-8651

AREA CODE 504 635


635-6094

February 28, 1985 RBG-20254 File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator U. S. Nuclear Regulatory Commission, Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Martin:

River Bend Station - Unit 1 Docket No. 50-458 Final Report/DR-239



Gulf States Utilities Company (GSU) has completed its evaluation of DR-239 concerning a high drywell pressure automatic isolation signal which was not provided on the Residual Heat Removal System (RHR) upper containment pool valves (E12-F037A&B). The valves are presently provided with a signal that prevents them from opening when the reactor pressure is greater than 135 psig. Since the RHR A&B loops are not required to perform a Low Pressure Coolant Injection function when the reactor is below the 135 psig level, the automatic isolation of these valves is not required below this level. GSU has therefore determined this condition is not reportable under 10CFR50.55(e). However, Field Deviation and Disposition Request LDI-1732 was issued to change the isolation signal. Engineering and Design Coordination Report Nos. C-68,578, C-68,656, and C-53,011 have been issued to implement this change.

Sincerely,

L. a. England

J. E. Booker

Manager-Engineering,

Nuclear Fuels & Licensing

River Bend Nuclear Group

JEB/PJD/trp

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

IE-27