This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the staff on this date.

ty: Commonwealth Edison Company

Byron Nuclear Power Station, Unit 1

Byron, IL 61010

Docket No: 50-454

Licensee Emergency Classification: Notification of an Unusual Event

Alert

Site Area Emergency
General Emergency

xx Not Applicable

Subject: ERRONEOUS NEWS REPORTS OF "LEAK" AT BYRON 1

Because of a nuclear instrumentation problem at Byron Unit 1, some 1500 construction workers were sent home on November 16, 1984, in an effort to eliminate potential sources of electrical "noise". Area news media apparently learned of this and misunderstood the situation. Some news reports were broadcast about a "leak" at the Byron site; other news reports, however, have correctly described the situation.

The licensee has been unable to complete fuel loading for Unit 1 because of excessive electrical "noise" in a portion of the nuclear instrumentation (source range monitor) used to monitor the reactor core during fuel loading. In an effort to reduce electrical interference from ongoing work on both Units 1 and 2, the licensee dismissed the night shift construction workers and sent the day shift workers home when they reported for work. Virtually all non-essential work has been stopped on the two units until the electrical interference problem can be corrected.

fuel loading began November 2, 1984, and only 8 of the 193 fuel assemblies remain to be laced in the core. The licensee plans to complete fuel loading on November 16 if the interference problem is resolved.

The resident inspector is on-site, monitoring licensee fuel loading activities.

The licensee and Region III (Chicago) have responded to news media inquiries in an effort to correct the misinformation.

The State of Illinois will be notified.

Region III was informed of the erroneous news reports at 9 a.m., November 16, 1984. This information is current as of that time.

CONTACT:

J. Strasma

FTS 388-56/4

J. Streeter FTS 388-5184

8411260281 841116 PDR I&E PNO-III-84-096 PDR

DISTRIBUTION:

H. St. 1 CC Chairman Palladino Comm. Roberts Comm. Asselstine Sem. Bernthal Zech MNPB 10 30 EDO PA MPA ELD

Phillips 10 32 NRR

Air Rights 10.55

E/W 10:14 1E 01A

NMSS RES

AEOD

18AC 10 49

MAIL: TE:3

Willste 10:35

DOT: Trans Only 0

ACRS CA PDR

Regions 110 37, 1110 42 110 43, VID 45

Licensee (Corporate Office)10.58