

APPENDIX B

U. S. NUCLEAR REGULATORY COMMISSION
REGION IV

NRC Inspection Report: 50-267/84-23

License: DPR-34

Docket: 50-267

Licensee: Public Service Company of Colorado
P. O. Box 840
Denver, Colorado 80201

Facility Name: Fort St. Vrain Nuclear Generating Station (FSV)

Inspection At: Platteville, Colorado

Inspection Conducted: August 27-31, 1984

Inspector: R. A. Caldwell 10-1-1984
R. A. Caldwell, Physical Security Specialist Date

Approved: R. E. Hall 10/6/84
R. E. Hall, Acting Chief, Nuclear Materials Safety and Safeguards Branch Date

R. E. Ireland for 10/24/84
R. E. Ireland, Acting Chief, Special Projects and Engineering Section Date

Inspection Summary

Inspection Conducted August 27-31, 1984 (Report 50-267/84-23)

Areas Inspected: Routine, unannounced inspection of management effectiveness - security program; locks, keys and combinations; detection aids - protected areas; and detection aids - vital areas. The inspection involved 37 inspector-hours onsite by one NRC inspector.

Results: Within the four areas inspected, two violations were identified (locks, keys, and combinations - paragraph 3, detection aids - protected area - paragraph 4).

8411260496 841024
PDR ADOCK 05000267
G PDR

ENCLOSURE CONTAINS ~
SAFEGUARDS INFORMATION.
UPON SEPARATION THIS
PAGE IS DECONTROLLED.