




GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

March 1, 1985
RBG- 20297
File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Martin:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-242

An interim or final status report concerning the fracture of a pinion gear in a motor operator supplied by Limitorque for a safety related valve in the Residual Heat Removal System will be provided by March 28, 1985.

Sincerely,

J. E. Booker
for J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JEB/PJD/lp

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

8503150119 850301
PDR ADOCK 05000458
S PDR

EE-27
1/0