In Reply Refer To: Dockets: 50-498/84-12 50-499/84-12

Houston Lighting & Power Company ATTN: G. W. Oprea, Jr. Executive Vice President P. O. Box 1700 Houston, Texas 77001

## Gentlemen:

This refers to the inspection conducted under the Resident Inspection Program by Messers. D. P. Tomlinson, D. R. Carpenter, and L. E. Ellershaw of this office during the period August 1 - September 30, 1984, of activities authorized by NRC Construction Permits CPPR-128 and 129 for the South Texas Project, Units 1 and 2, and to the discussion of our findings with members of your staff at the conclusion of the inspection.

Areas examined during the inspection included a review of previously identified inspection findings, site tours, IE Bulletin followup, and allegation followup. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the NRC inspectors. These findings are documented in the enclosed inspection report.

Within the scope of the inspection, no violations or deviations were identified.

One unresolved item is identified in paragraph 4 of the enclosed inspection report.

We have also examined actions you have taken with regard to previously identified inspection findings. The status of these items is identified in paragraph 3 of the enclosed inspection report.

8411280248 841123 PDR ADOCK 05000498 Q PDR

	18	40	Ge .	A	1	1 E'
OFFICE SURNAME DAGE	SRI/RPB1/B DTomTinson/ 10/13/84	RRI/RPB1B ik D€arpenter 10/,3/84	SRV RPB2/A LETTershaw 10/12/84	RP81/A JPJaudon VI 10/1/84	RPB1 EHJohnson 14/1/84	***************************************
NRC FORM	318 (10-80) NRCM 024	10	FEICIAL RECO	ORD CORY		

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

J. P. Jauden

E. H. Johnson, Chief Reactor Project Branch 1

Enclosure:

 Appendix - NRC Inspection Report 50-498/84-12 50-499/84-12

cc w/enclosures:
Houston Lighting & Power Company
ATTN: J. H. Goldberg, Vice President
Nuclear Engineering and Construction
P. O. Box 1700
Houston, Texas 77001

Brian Bersick, Esq.
Asst. Actorney General
Environmental Protection Div.
P. O. Box 12548, Capitol Station
Austin, Texas 78711

Mr. Lanny Sinkin 114 West 7th, Suite 220 Austin, Texas 70701

bcc to DMB (IEO1)

bcc distrib. by RIV:

RPB1 Resident Inspector
RPB2 Section Chief (RPB1/A)
EP&RPB R. Denise, DRS&P

MIS SYSTEM RIV File TEXAS DEPT. OF HEALTH RESOURCES

R. Martin, RA C. Wisner, PAO V. Nerses, NRR