



GULF STATES UTILITIES COMPANY

RIVER BEND STATION POST OFFICE BOX 220 ST. FRANCISVILLE, LOUISIANA 70775

AREA CODE 504 635-3237 387-4257

November 8, 1984


RBG- 19390

File Nos. G9.5, G9.25.1.1

Mr. Robert D. Martin, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Dear Mr. Martin:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-182



An interim or final status report concerning a Limitorque motor operator failure on a feedwater isolation valve will be provided by January 30, 1985.

Sincerely,

for J. E. Booker
Manager-Engineering,
Nuclear Fuels & Liscensing
River Bend Nuclear Group

RJD
JEB/PJD/trp

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

8411280410 841108
PDR ADOCK 05000458
S PDR

IE-27.10