

NOV 16 1984


Docket No. 50-341

The Detroit Edison Company
ATTN: Wayne H. Jens
Vice President
Nuclear Operations
6400 North Dixie Highway
Newport, MI 48166

Gentlemen:

Thank you for your letter dated September 27, 1984, informing us of the steps you have taken to correct the noncompliance which we brought to your attention in our letter dated August 14, 1984. We find your reported corrective action acceptable. However, in regard to item 84-17-01-a. and your conclusion that the correct procedure (3071-128 EP-4-4) and splicing kit were used; we note that your response does not acknowledge that the correct procedure and equipment were used in direct response to the NRC inspectors identification that your personnel were initially using the wrong procedures and equipment. We will examine these matters during a future inspection.

Sincerely,



W. S. Little, Chief
Engineering Branch

cc w/ltr dtd 9/27/84:
L. P. Bregni, Licensing
Engineer
P. A. Marquardt, Corporate
Legal Department
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
Harry H. Voigt, Esq.

RIII # for Naidu/lc 11/15/84	RIII # Falevits	RIII # for Gautam	RIII C. J. [unclear] Tany	RIII CK Knop	RIII [unclear] Williams	RIII NA [unclear] Little 11/15
---------------------------------------	-----------------------	-------------------------	---------------------------------	--------------------	-------------------------------	---

8411280474 841116
PDR ADOCK 05000341
Q PDR

1601
|||