


October 9, 1984 RBG- 19148 File Nos. G9.5, G9.25.1.1 * Corrected Copy

Mr. Robert D. Martin, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Martin:

River Bend Station Unit 1 Docket No. 50-458 Interim Report/DR-206 *



An interim or final status report concerning the lubricant in the two fuel pool cooling pumps and motors will be provided by December 12, 1984.

Sincerely,

J. E. Booker

Manager-Engineering, Nuclear Fuels & Licensing River Bend Nuclear Group

JEB/PJD/1p

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

8411290034 841009 PDR ADDCK 05000458 PDR S

TE-27