A NO.

#### UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011 8064 AUG | 7 1992

#### SAFEGUARDS INFORMATION

Docket Nos. 50-445 50-446 License No. NPF-87 Construction Permit No. CPPR-127

TU Electric
ATIN: W. J. Cahill, Jr., Group Vice President
Nuclear Engineering and Operations
Skyway Tower
400 North Olive Street, L.B. 81
Dallas, Texas 75201

Gentlemen:

SUBJECT: NRC INSPECTION REPORT 50-445/92-30; 50-446/92-30 (NOTICE OF VIOLATION)

This refers to the inspection conducted by Messrs. A. B. Earnest and T. W. Dexter of this office during the period July 27-31, 1992. The intection included a review of activities authorized for your Comanche Peak Steam Electric Station. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspectors.

Based on the results of this inspection, one of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violation is of concern in that adequate barriers and detection aids were not maintained to prevent unauthorized and undetected access to a vital area.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your

200007
DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION.
UPON SEPARATION THIS
PAGE IS DECONTROLLED.

9208210053 920817 PDR ADOCK 05000445 9 PDR



## SAFEGUARDS INFORMATION

response, you should document the specific actions and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with regulatory requirements.

The inspectors also identified a weakness in the implementation of your fitness-for-duty program concerning the potential for early notification of at least some of your employees selected for random drug tests. We request that you respond in writing within 30 days of the date of this letter with your evaluation of this potential weakness, identifying any corrective actions that you have either taken or plan to take.

The material enclosed herewith contains Safeguards Information as defined by 10 CFR Part 73.21 and it disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. Therefore, the material with the exception of the report cover page which is an inspection summary, will not be placed in the Public Document Room. Should you have any mestions concerning this inspection, we will be pleased to discuss them with you.

Sincerely.

A. S. Beach, Director/ Division of Reactor Projects

Enclosures:

1. Appendix A - Notice of Violation

Appendix B - Inspection Report 50-445/92-30

50-445/92-30 50-446/92-30

cc w/Notice of Violation and summary page only:

TU Electric

ATTN: Roger D. Walker, Manager of Regulatory Affairs for Nuclear Engineering Organization

Skywwy Tower 400 North Olive Street, L.B. 81 Dallas, Texas 75°01

SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION.
UPON SEPARATION THIS
PAGE IS DECUNTROLLED.

### -3- DOCUMENT CONTAINS SAFEGUARDS INFORMATION

Juanita Ellis President - CASE 1426 South Polk Street Dallas, Texas 75224

GDS Associates, Inc. Suite 720 1850 Parkway Place Marietta, Georgia 30067-8237

TU Electric Bethesda Licensing 3 Metro Center, Suite 610 Bethesda, Maryland 20814

Jorden, Schulte, and Burchette ATTN: William A. Burchette, Esq. ounsel for Tex-La Electric Cooperative of Texas 1025 Thomas Jefferson St., N.W. Washington, D.C. 20007

Newman & Holtzinger, P.C. ATTN: Jack R. Newman, Esq. 1615 L. Street, N.W. Suite 1000 Washington, D.C. 20036

Texas Department of Labor & Standards ATTN: G. R. Bynog, Program Manager/ Chief Inspector Boiler Division P.O. Box 12157, Capitol Station Austin, Texas 78711

Honorable Dale McPherson County Judge P.O. Box 851 Glen Rose, Texas 76043

Texas Radiation Control Program Director 1100 West 49th Street Austin, Texas 7875b

SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS SAFEGUARDS INFORMATION. UPON SEPARATION THIS PAGE IS DECONTROLLED. TU Electric

#### SAFEGUARDS INFORMATION

Owen L. Thero, Presider Quality Technology Company Lakeview Mobile Home Park, Lot 35 4793 E. Loop 820 South Fort Worth, Texas 76119

SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION.
UPON SEPARATION THIS
PAGE IS DECONTROLLED.

# SAFEGUARDS NFORMATION

bcc copy of entire report:

RIV Security File (Original copy of report)
Elaine Koup, RSGB/NRR (9D24)
J. L. Milhoan, RA
Resident Inspector
FIPS Security File
G. F. Sanborn, EO

bcc copy of letter, NOV, and inspection summary only:

DMB IE-04

DRS

Lisa Shea (4503)

Project Engineer, DRP/2

MIS

RSTS Coordinator

Division Director, DRP

M. Fields, NRR Project Manager

J. Wilson, NRR Project Manager

		- 145		
			./	
		-	H	MARK WALL DO THE OUT
RIV: FIPS	C:FIPS	D:DRSS	D. DRP	
ABEarnest Phh	BMurray (	LJCallan	ABBeach	
8//3/92	8/13/52	8/13/92	V ( / 14/92	

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

ENCLOSURT CONTAINS SAFEGUARDS INFORMATION. UPON SEPARATION THIS PAGE IS DECONTROLLED.

#### SAFEGUARDS INFORMATION

bcc copy of entire report:

RIV Security File (Original copy of report)

Elaine Koup, RSGB/NRR (9D24)

J. L. Milhoan, RA

Resident Inspector

FIPS Security File

G. F. Sanborn, EO

bcc copy of letter, NOV, and inspection summary only:

DMB IE-04

DRS

Lisa Shez (4503)

Project Engineer, DRP/B


MIS

RSTS Coordinator

Division Director, DRP

M. Fields, NRR Project Manager

J. Wilson, NRR Project Manager



SAF ARDS INFORMATION

ENCLOSURE CONTAINS SAFEGUARDS INFORMATION. UPON SEPARATION THIS PAGE IS DECONTROLLED.