

yellow

MAR 1 1985

Duke Power Company
ATTN: Mr. H. B. Tucker, Vice President
Nuclear Production Department
422 South Church Street
Charlotte, NC 28242

Gentlemen:

SUBJECT: REPORT NOS. 50-369/85-04 AND 50-370/85-04

On February 4 - 8, 1985, NRC inspected activities authorized by NRC License Nos. NPF-9 and NPF-17 for your McGuire facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

Your attention is invited to unresolved items identified in the inspection report. These matters will be pursued during future inspections.

Should you have any questions concerning this letter, please contact us.

Sincerely,

bl

Virgil L. Brownlee, Chief
Reactor Projects Branch 2
Division of Reactor Projects

Enclosure:
Inspection Report Nos. 50-269/85-04
and 50-370/85-04

cc w/encl:
M. D. McIntosh, Station Manager
C. F. York, Division Manager

bcc w/encl:
NRC Resident Inspector
Document Control Desk
State of North Carolina

8503200049 850301
PDR ADOCK 05000369
Q PDR

RII
WJR
WRoss:sa
02/26/85

RII
JB
JBlake
02/26/85

RII
AKH
AHerd
02/28/85

AKB

IEO1