

ENCLOSURE 1

NOTICE OF VIOLATION

Duke Power Company
McGuire

Docket No. 50-369
License No. NPF-9

The following violation was identified during an inspection conducted on August 20 - September 20, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Code of Federal Regulations, Part 50.73, "Licensee Event Report System," Part (2)(V)(c) states, in part, that the licensee shall report within 30 days of any event or condition that alone could have prevented the fulfillment of the safety function of structures or systems that are needed to control the release of radioactive material.

Contrary to the above requirement, containment integrity was degraded when containment spray vent valve INS-68 was left open and this event was not reported as required.

This is a Severity Level IV violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: NOV 1 1984

8503200152 850222
PDR ADOCK 05000369
Q PDR