

ENCLOSURE 1

NOTICE OF VIOLATION

Tennessee Valley Authority
Sequoyah Units 1 and 2

Docket Nos. 50-327 and 50-328
License Nos. DPR-77 and DPR-79

The following violation was identified during an inspection conducted on November 6 - December 5, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 6.8.1 requires that written procedures be established, covering activities referenced in Appendix A of Regulatory Guide 1.33, Revision 2, February 1978. Paragraph 3 of Appendix A requires specific procedures for the Emergency Core Cooling System (ECCS). System Operating Instruction (SOI)-63.1 was established to satisfy this requirement.

Contrary to the above, adequate procedures were not established in that Valve Checklists 63.1A-3 and 63.1A-4, Revision 26, of SOI-63.1, Emergency Core Cooling System, Revision 30, each failed to list a level transmitter root valve for the cold leg accumulators.

This is a Severity Level V violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: DEC 28 1984

8503200232 840226
PDR ADOCK 05000327
Q PDR