

JUL 05 1995

75-27

REGIONAL TECHNICAL ASSISTANCE REQUEST FORM

Date: June 21, 1995

Mail or E-Mail to: Don Cool (DAC), Mail Stop: 6H3-OWFN, If E-mail, cc:CLE  
Division of Industrial and Medical Nuclear Safety, NMSS

From: *JRM 6/21/95* John R. Madera (JRM4), Region III  
Chief, Nuclear Materials Licensing Section

Licensee: Syncor Corporation  
License No. 34-16654-01MD

X Control No. 398441

X Letter dated: May 23, 1995

☐ Suggested change in licensing procedure (enclosed):

X Problem/Issue: Licensee requests exemption from 10 CFR 30.50(b)(2) reporting requirements for fume hood failures, if no employee is exposed to greater than 20 DAC-hours.

X Action Required: Evaluate appropriateness of request, and if approved, please provide recommended wording of license condition.

X Recommended Action (with revisions): X Approve or ☐ Reject  
I concur with licensee that failure of the standard laboratory fume hood does not normally constitutes significant hazard to the health and safety of either the public or licensee employees and would be supported by air sampling analysis and bioassay program.

Remarks:

Headquarters Reviewer: \_\_\_\_\_

Regional Reviewer: Loren J. Hueter

Reviewer Code: R8

Reviewer Phone No.: (708) 829-9829

Request Needed by: July 31, 1995

FAX No.: (708) 515-1259

Form TAR-10 8/93

9508160138 1P XA 3/29/96