

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

APR 02, 1984


Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Re: RII:WCL
50-413/83-40
50-414/83-34

Dear Mr. O'Reilly:

In my February 15, 1984 letter to you supplementing the original response to Violation No. 413/83-40-01, it was stated that all additional corrective action would be complete by April 2, 1984. Due to an underestimation of the amount of additional work required, all of the necessary corrective action has not been accomplished. The remaining work will be completed by April 23, 1984.

Very truly yours,



Hal B. Tucker

RWO/php

cc: NRC Resident Inspector
Catawba Nuclear Station

Palmetto Alliance
2135 1/2 Devine Street
Columbia, South Carolina 29205

Mr. Robert Guild, Esq.
Attorney-at-Law
P. O. Box 12097
Charleston, South Carolina 29412

8412010026 840402
PDR ADOCK 05000413
Q PDR

IE01 1/0