

ENCLOSURE 1

NOTICE OF VIOLATION

Virginia Electric and Power Company  
North Anna

Docket Nos. 50-338 and 50-339  
License Nos. NPF-4 and NPF-7

The following violation was identified during an inspection conducted on January 6 - February 5, 1985. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Channel Check as defined in Section 1.4 of the Technical Specifications, states, in part, "A Channel Check shall be the qualitative assessment of channel behavior during operation by observation. This determination shall include, where possible, comparison of the channel indication and/or status with other indication and/or status derived from instrumentation channels measuring the same parameter."

Technical Specification 4.3.1.1.1 requires in Table 4.3-1 that overtemperature Delta T and overpower Delta T protection be verified operable every 12 hours by the performance of a Channel Check. Additionally, technical specification 4.3.3.5 requires in table 4.3-6 that auxiliary shutdown panel steam generator level be verified operable every 31 days by the performance of a Channel Check.

Contrary to the above, the licensee failed to meet the surveillance requirements in that:

- A. Unlike parameters were compared when performing the Channel Checks of  $\Delta T$  instruments TI-1-412A, TI-1-422A and TI-1-432A (TI-2-412, TI-2-422A and TI-2-432A for Unit 2)
- B. When performing the Channel Checks of Steam Generator Level instruments LI-1477B, LI-1487B and LI-1497B (LI-2477B, LI-2487B and LI-2497B for Unit 2) unlike parameters were also compared.

This is a Severity Level IV violation and applies to both units.

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Virginia Electric and Power Company 2  
North Anna

Docket Nos. 50-338 and 50-339  
License Nos. NPF-4 and NPF-7

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: FEB 22 1965