



November 14, 1984

50-373

James G. Keppler Regional Administrator Region III U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Sir:

This special report is submitted in accordance with LaSalle Unit 1 Operating License NPF-11, Appendix A, Technical Specifications 3.7.6 and 6.6.c.

On October 20, 1984, after the completion of fire door surveillance, LTS-1000-14, various fire doors did not meet the inspection criteria as outlined in the surveillance procedure. In accordance with the Action Statement of Technical Specification 3.7.6, the doors were declared inoperable.

An hourly fire watch was established in the affected areas in addition to generating a Work Request to fix the above mentioned doors. The work is expected to be completed by December 1, 1984, at which time the doors will be declared operable upon satisfactorily being re-inspected in accordance with LTS-1000-14.

G.J. Diederich Superintendent

LaSalle County Station

GJD/JSK/kg

xc: U.S. NRC Document Control Desk INPO - Records Center File/NRC

NOV 2 1 1984