Docket No. 50-247

Consolidated Edison Company of
New York, Inc.
ATTN: Mr. John D. O'Toole
Vice President - Nuclear
Engineering and Quality Assurance
4 Irving Place
New York, New York 10003

Gentlemen:

Subject: Inspection No. 50-247/84-31

This refers to the routine safety inspection conducted by Mr. Peter C. Wen of this office on October 15-19, 1984, at Indian Point Nuclear Station Unit 2, of activities authorized by NRC License No. DPR-26 and to the discussions of our findings held by Mr. Wen with Mr. S. Quinn of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the NRC Region I Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no violations were observed.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

Original Signed By: Jacque P. Durr

Thomas T. Martin, Director
Division of Engineering and
Technical Programs

Enclosure: NRC Region I Inspection Report Number 50-247/84-31

8412040145 841129 PDR ADDCK 05000247 PDR ADDCK 05000247 cc w/encl:

C. W. Jackson, Vice President, Nuclear Power

M. Blatt, Director, Regulatory Affairs

W. D. Hamlin, Assistant to Resident Manager (PASNY)

F. Matra, Resident Construction Manager R. L. Spring, Nuclear Licensing Engineer

Director, Power Division Thomas J. Farrelly, Esquire

K. Burke, General Manager, Administrative Services

Brent L. Brandenburg, Assistant General Counsel

Public Document Room (PDR)

Local Public Document Room (LPDR)

Nuclear Safety Information Center (NSIC)

NRC Resident Inspector

State of New York

bcc w/encl:

Region I Docket Room (with concurrences) Senior Operations Officer (w/o encls)

L. Norrholm, DPRP Section Chief, #2B

RI:DETP Wen/kl 11/15/84 PcW RI:DETP RI:DETP Bettenhausen Ebneter 11/23/84 11/24/84

OFFICIAL RECORD COPY

DL50-247/84-31 - 0002.0.C 11/14/84