

TEXAS UTILITIES GENERATING COMPANY
SKYWAY TOWER • 400 NORTH OLIVE STREET, L.B. 81 • DALLAS, TEXAS 75201

BILLY R. CLEMENTS
VICE PRESIDENT, NUCLEAR OPERATIONS

March 27, 1985
TXX-4448

Mr. D.R. Hunter, Chief
Reactor Project Branch 2
U.S. Nuclear Regulatory Commission
Office of Inspection & Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012

Docket No.: 50-445

COMANCHE PEAK STEAM ELECTRIC STATION
ELECTRICAL BUTT SPLICES
QA FILE: CP-85-07, SDAR-168
FILE NO.: 10110

Dear Mr. Hunter:

On February 28, 1985 we verbally notified your Mr. D. Hunnicutt of a deficiency regarding the reinspection of electrical cable butt splices identified by the Technical Review Team (TRT) as Items I.a.2 and I.a.3. We have submitted an interim report logged TXX-4432 dated March 5, 1985.

We are continuing our evaluation and anticipate completion by June 5, 1985.


Very truly yours,

Billy R. Clements

BRC:tlg

cc: NRC Region IV (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)
U.S. Nuclear Regulatory Commission
Washington, DC 20555



85-109
8504050368 850327
PDR ADOCK 05000445
S PDR

A DIVISION OF TEXAS UTILITIES ELECTRIC COMPANY

IL-27

1/0