

Donald F. Schnell Vice President

December 27, 1984

Mr. Harold R. Denton, Director Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, DC 20555

ULNRC- 1004

Dear Mr. Denton:

DOCKET NUMBER 50-483 CALLAWAY PLANT, UNIT 1 ADDITION TO TECHNICAL SPECIFICATION TABLE 4.11-1

- References: 1) ULNRC-937 dated October 3, 1984
 - 2) ULNRC-993 dated December 6, 1984

The referenced letters concern our Technical Specification change request associated with the addition of two Batch Waste Release Tanks. Transmitted herewith are piping and instrumentation diagrams which depict the additional tanks and their associated piping connections. These drawings were requested by NRC Staff (R. Fell and J. Stevens) in a telephone conversation on December 20, 1984.

If further information is needed, please contact us.

Very truly yours,

Donald F. Schnell

DS/RJS/1kr

Attachments

8501020335 84122 PDR ADDCK 050004

Agriland Date Che 1 2

STATE OF MISSOURI)

CITY OF ST. LOUIS)

Robert J. Schukai, of lawful age, being first duly sworn upon oath says that he is General Manager-Engineering (Nuclear) for Union Electric Company; that he has read the foregoing document and knows the content thereof; that he has executed the same for and on behalf of said company with full power and authority to do so; and that the facts therein stated are true and correct to the best of his knowledge, information and belief.

Dapares

General Manager-Engineering

Nuclear

SUBSCRIBED and sworn to before me this 27th day of Duember 1984

BARBARA J. PFAFF

NOTARY PUBLIC, STATE OF MISSOURI MY COMMISSION EXPIRES APRIL 22, 1985

ST. LOUIS COUNTY

cc: Gerald Charnoff, Esq.
Shaw, Pittman, Potts & Trowbridge
1800 M. Street, N.W.
Washington, D.C. 20036

Nicholas A. Petrick Executive Director SNUPPS 5 Choke Cherry Road Rockville, Maryland 20850

John H. Neisler Callaway Resident Office U.S. Nuclear Regulatory Commission RR#1 Steedman, Missouri 65077

William Forney
Division of Projects and
Resident Programs, Chief, Section 1A
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Bruce Little Callaway Resident Office U.S. Nuclear Regulatory Commission RR#1 Steedman, Missouri 65077

Jan Stevens
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Mail Stop P-316
7920 Norfolk Avenue
Bethesda, MD 20014

Attachment to ULNRC-1004

List of Drawings

84-05-86-M-22HB05, Rev. 1

ECN 84-05-86-M-02HF02, Rev. 10, Seq. 1

ECN 84-05-86-OP-M-02HF03, Rev. 3, Seq. 2

ECN 84-05-86-0P-M-02BM04, Rev. 4, Seq. 1

ECN 84-05-86-M-22HB03, Rev. 0, Seq. 1

ECN 84-05-86-0P-M-22AN01, Rev. 4, Seq. 1

SEE

APERTURE

CARDS

*OVERSIZED DRAWINGS

(ADDITIONAL DOCUMENT PAGES FOLLOW)

APERTURE CARD NOT 8501020340

AVAILIBILITY



CF

HOLD

NUMBERS OF PAGES.



ENGINEERING CHANGE NOTICE

7820			12-18-	84
	TYPE OF DO	CUMENT CHANG	GED	
	CMP NO.	DOC NO.	REV/SUB	SEL
ECN NO.	84-05-86	M-02HF02	10	1

Page_Lot_L

File No. 0/7/./

REASON FOR CHANGE

CMP 84-05-86

DESCRIPTION OF CHANGE

(BEFORE CHANGE)

(COORD. B-2)

PLANT DISCHARGE LINE ----> M-02HE03 (D-4)

(AFTER CHANGE)

DISCHARGE
MONITOR TANKS
---- M·22H805

3-A-102880

RESPONSIBLE ENGINEER DRAWING DRAWN CHECKED SUPERVISOR CONTROL ED BICK HACKNEY LAUNHARDT REVIEW SUPERVISING MANAGER REVIEWING ENGINEER SUPERINTENDENT MANAGER -ENGINEER AND NUCLEAR ENGINEERING AFPROVAL NA NA NA NA NA



ENGINEERING CHANGE NOTICE

WORK ORDER 1820		OATE OF ECN	DATE OF ECN /2-/9-84		
		AWING	SED .		
1111	CMP NO.	DOC NO.	REV/SUB	SEQ	
ECN NO.	84-05-86	M-OZHFO3	3	2	
File !	No.	Page			

REASON FOR CHANGE

SUPERVISING

NA

ENGINEER

MANAGER


NA

REVIEW


APPROVAL

ANO

CMP 84-05-86



AFTER CHANGE



SUPERINTENDENT

NA

REVIEWING ENGINEER

NA

MANAGER-

NUCLEAR ENGINEERING

NA



ENGINEERING CHANGE NOTICE

7820			OF ECN 12-18-84		
		CUMENT CHANG	SEO		
7777	CMP NO.	DOC NO.	REV/SUB	SEQ	
ECN NO.	84.05.86	M-02BM04	4	1	
File	No. 0171.1	Page	_/ of _/		

REASON FOR CHANGE

CMP 84-05-86

DESCRIPTION OF CHANGE

BEFORE CHANGE

(coord. 0-1)

. HB-220-HCO-4" -> M-02HB03 \((0-4)

AFTER CHANGE

(COORD. D-1)

DISCHARGE MONITOR TANKS M-22HB05 (B-3)

I RESPONSIBLE ENGINEER CHECKED DRAWING DRAWN CONTROL ED BICK HACKNEY SUPERVISING SUPERINTENDENT REVIEW MANAGER ENGINEER DA AND NA

LAUNHARDT REVIEWING ENGINEER MANAGER-

SUPERVISOR

APPROVAL.

NA

NA

NA

NUCLEAR ENGINEERING NA



ENGINEERING CHANGE NOTICE

WORK ORDER 7820		OATE OF ECN	OATE OF ECN /2-/8-84		
		UMENT CHANCE	E0 -		
2212	CMP NO.	COC NO.	REV/SUB	SEQ	
ECN NO.	84-05-86	M-22HB03	0	1	
File N	ia. 0/7/./	Page			

REASON FOR CHANGE CMP 84-05-86 DESCRIPTION OF CHANGE BEFORE CHANGE DESCRIPTION OF STREET (0-1) ##514 7840H018 41-409-3" 2T \$ 4-01H102 Z 5 (3°) BURIED FROM LOW STLUTS
SMITCH BY SITE
NA RADWEST'S BUILDING #912 15 1:4 IP DISCHARGE LINE V403 SE-STAGES 67 SITE 4/4 (14-31) MOTE 13 1023 70-21 -AM-023-MED-F Y 143 Lia (F) (18 HOTE IS 289-68-40 ¥347 TO OFFITAL 70-HCO-Z" PALEL SP-086 AFTER CHANGE DISCHARGE MONITOR TANKS M-22HB05 V092 (B-1) $C \rightarrow \infty$ V349 V347 170-HCO-2" V348 RESPONSIBLE CRAWN CHECKED SUPERVISOR ENGINEER CRAWING CONTROL LAUNHARDT EO BICK HACKNEY MANAGER SUPERVISING SUPERINTENDENT REVIEWING ENGINEER MANAGER -REVIEW NUCLEAR ENGINEERING ENGINEER QA

NA

NA

NA

NA

-102880 1

<! 3 4

AND

APPROVAL

NA



ENGINEERING CHANGE NOTICE

WORK ORDER DATE OF ECN /2-/8-84 7820 TYPE OF DOCUMENT CHANGED DRAWING DOC NO. REV/SUB SEQ CMP NO. ECN 84.05.86 NO. M-22 ANOI

File No. 3456 0/7/./ Page____ot___

REASON FOR CHANGE

CMP 84-05-86

DESCRIPTION OF CHANGE

BEFORE CHANGE

(COORD. B-2)

HF-055-HCD-1" LIQ RADWASTE DISCHARGE MONITOR FLUSH LINE M-02HB03 (6-5)

AFTER CHANGE

(600RD. 13.2)

HF-055-HCD-1" -RE-18 FLUSH LINE M-22HB05 (13-1)

A-102880 3

4

I RESPONSIBLE ENGINEER DRAWN CHECKED SUPERVISOR DRAWING CONTROL HACKNEY EO BILL LAUNHARDT REVIEWING ENGINEER MANAGER -SUPERINTENDENT REVIEW SUPERVISING MANAGER NUCLEAR ENGINEERING ENGINEER 04 AND NA NA NA NA APPROVAL. NA