

SAFEGUARDS INFORMATION

NUCLEAR REGULATORY COMMISSION

REGION II 101 MARIETTA STREET, N.W. ATLANTA, GEORGIA 30323

Report No.: 50-261/92-12

Licensee: Carolina Power and Light Company

P. O. Box 1551 Raleigh, NC 27602

Docket No.: 50-261

License No.: DPR-23

Facility Name: H. B. Robinson

Inspection Conducted: June 8-12, 1992

11:1:

W. J. Tobin Senior Safeguards Inspector

Date, Signed

Approved by: A

D. R. McGuire, Chief Safeguards Section

Nuclear Materials Safety and Safeguards Branch Division of Radiat on Safety and Safeguards

SUMMARY

Scope:

This routine, unannounced inspection was conducted in the area of Physical Security for Power Reactors; specifically Contingency Plans, Access Controls, Audits, and Power Supply. Two safeguards (reportable) events were reviewed. The licensee's corrective actions to two prior items were reviewed.

Results:

In the areas inspected, no violations or deviations were identified.

One non-cited violation (NCV) was identified regarding vital area doors being left in unsecured condition on two occasions.

Prior violations (92-04-01 and 02) were closed. An issue regarding the reliability of security equipment will remain open and will now include the licensee's testing of the security diesel under a full load.

The licensee's Security Program appears to remain adequate but is experiencing weaknesses in security shift supervisors' and officers' attention to access control procedural requirements.

9207080256 920701 PDR ADDCK 05000261 PDR

the all the parentle discounts
are parentled, and translated
and are parentled. When to parentled tracty
and are parentled to the parentled.

SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

Contingency planning appears well coordinated with offsite agencies, audits are thorough and reported to the correct level of management, and power supplies appear to be adequate but in need of testing under full load requirements.