



NUCLEAR REGULATORY COMMISSION

REGIONIV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

APR - 3 1996

Entergy Operations, Inc.

ATTN: J. W. Yelverton, Vice President Operations, Arkansas Nuclear One

1448 S.R. 333

Russellville, Arkansas 72801-0967

SUBJECT: PLANT PERFORMANCE REVIEW (PPR) - ARKANSAS NUCLEAR ONE

On March 11, 1996, the NRC staff completed the semiannual PPR of Arkansas Nuclear One. The staff conducts these reviews for all operating nuclear power plants to develop an integrated understanding of safety performance. The results are used by NRC management to facilitate planning and allocation of inspection resources. The PPR for Arkansas Nuclear One involved the participation of all technical divisions in evaluating inspection results and safety performance information for the period September 1995 to March 1996. PPRs provide NRC management with a current summary of licensee performance and serve as inputs to the NRC Systematic Assessment of Licensee Performance (SALP) and senior management meeting (SMM) reviews.

This letter advises you of our planned inspection effort resulting from the Arkansas Nuclear One PPR review. It is provided to minimize the resource impact on your staff and to allow for scheduling conflicts and personnel availability to be resolved in advance of inspector arrival onsite. The enclosure details our inspection plan for the next 8 months. The SALP period will be ending during this 8-month period. The rationale or basis for each inspection outside the core inspection program is provided so that you are aware of the reason for emphasis in these program areas. Resident inspections are not listed due to their ongoing and continuous nature.

We will inform you of any changes to the inspection plan. If you have any questions, please contact Terry Reis at 817/860-8185.

Sincerely,

J. E. Dyer, Director

Division of Reactor Projects

Dockets: 50-313

50-368

Licenses: DPR-51

NPF-6

Enclosure:

Inspection Plan

cc: Entergy Operations, Inc. ATTN: Executive Vice President & Chief Operating Officer P.O. Box 31995 Jackson, Mississippi 39286-1995

Entergy Operations, Inc.
ATTN: Vice President
Operations Support
P.O. Box 31995
Jackson, Mississippi 39286

ABB Combustion Engineering Nuclear Power ATTN: Manager, Washington Nuclear Operations 12300 Twinbrook Parkway, Suite 330 Rockville, Maryland 20852

County Judge of Pope County Pope County Courthouse Russellville, Arkansas 72801

Winston & Strawn 1400 L Street, N.W. Washington, D.C. 20005-3502

Arkansas Department of Health
ATTN: Director
Division of Radiation Control and
Emergency Management
4815 West Markham Street
Little Rock, Arkansas 72205-3867

Framatone Technologies
ATTN: Manager
Rockville Nuclear Licensing
1700 Rockville Pike, Suite 525
Rockville, Maryland 20852

bcc to DMB (IEO1) //

bcc distrib. by RIV:

L. J. Callan

DRP Director

Branch Chief (DRP/C)

Project Engineer (DRP/C)

Branch Chief (DRP\TSS)

Resident Inspector MIS System RIV File DRS-PSB

Leah Tremper (OC/LFDCB, MS: TWFN 9E10)

DOCUMENT NAME: G:\DRPDIR\SPPR\LTR96.ANO

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:DRP/C	AC: DRP/6	D:DRP	
RLNease; df New	TReistin	JEDyer W	
3/210/96	#/ 1/96	4/3/96	

OFFICIAL RECORD COPY

bcc to DMB (IEO1)

bcc distrib. by RIV:
L. J. Callan
DRP Director
Branch Chief (DRP/C)
Project Engineer (DRP/C)
Branch Chief (DRP\TSS)

Resident Inspector
MIS System
RIV File
DRS-PSB
Leah Tremper (OC/LFDCB, MS: TWFN 9E10)

DOCUMENT NAME: G:\DRPDIR\SPPR\LTR96.ANO

To receive copy of document, indicate in bex: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:DRP/C	AC: DRP/6	D:DRP	
RLNease; df N	TReisten	JEDyer WIL	
3/210/96	\$1 1/96	4/3/96	

OFFICIAL RECORD COPY

ARKANSAS NUCLEAR ONE

INSPECTION PLAN

IP - Inspection Procedure
II - Temporary Instruction
Core Inspection - Minimum NRC Inspection Program (mandatory all plants)

INSPECTION	TITLE/ PROGRAM AREA	NUMBER OF INSPECTORS	PLANNED INSPECTION DATES	TYPE OF INSPECTION COMMENTS
IP 93808	Integrated Performance Assessment Process	5	4/15-26/96	Core Inspection
IP 60851 IP 60854 IP 60855 IP 83750	ISFSI Dryrun	5	5/6-9/96	Core Inspection¹
IP 60855	ISFSI Actual Loading	3	TBD	Core Inspection
IP 82701	EP Operational Status	2	5/13-17/96	Core Inspection
IP 37550	Engineering	2	5/20-24/96	Core Inspection
IP 37550	Engineering	2	6/3-7/96	Core Inspection
IP 81700	EP Full Scale Exercise	5	8/12-16/96	Core Inspection
TI 109	GL 89-10	2	9/16-20/96	Safety Initiative
IP 73753	Inservice Inspection	1	9/23-27/96	Core Inspection
TI 109	GL 89-10	2	9/30 - 10/4/96	Safety Initiative
IP 83750	Radiation Protection	2	10/21-25/96	Core Inspection

Mandatory at all plants performing ISFSI activities