SAFEGUARDS INFORMATION

DAB

JAN 0 2 1985

Docket No. 50-341

The Detroit Edison Company ATTN: Wayne H. Jens Vice President Nuclear Operations 6400 North Dixie Highway Newport, MI 48166

Gentlemen:

This refers to the routine preoperational safeguards inspection conducted by Messrs. T. J. Madeda, J. R. Kniceley, and G. L. Pirtle of this office on November 26-30 and December 10-14, 1984, of activities at Enrico Fermi Atomic Power Plant, Unit 2, authorized by NRC Construction Permit No. CPPR-87 and to the discussion of our findings with Mr. S. H. Leach and other members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection. However, the inspection did note a serious concern regarding your unsuccessful attempts to adequately reduce the intrusion alarm rate. This situation warrants senior management attention because it could adversely impact our recommendation for license issuance. Your attention is drawn to Sections 2 and 19 of the enclosed report.

Areas examined during this inspection concern a subject matter which is exempt from disclosure according to Section 73.21(c)(2) of the NRC's "Rules of Practice," Part 73, Title 10, Code of Federal Regulations. This information must be handled and protected in accordance with the provisions of 10 CFR 73.21. Consequently, our report of this inspection will not be placed in the Public Document Room.

9501070374 850102 PDR ADDCK 05000341 G PDR IE04 1.

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
Alpage is Decontrolled

SAFEGUARDS INFORMATION

The Detroit Edison Company

2

JAN 0 2 1995

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

W L. Axelson, Chief Nuclear Materials Safety and Safeguards Branch

Enclosure: Inspection Report No. 50-341/84-60(DRSS) (UNCLASSIFIED SAFEGUARDS INFORMATION)

cc w/encl:
L. P. Bregni, Licensing
Engineer
P. A. Marquardt, Corporate
Legal Department
IE File
IE/DQASIP/ORPB
IE/ES
NMSS/SGPL
NRR/DL/SSPB
ACRS

cc w/encl, w/o UNCLASSIFIED
SAFEGUARDS INFORMATION:
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
Harry H. Voigt, Esq.

Amadeda/rr 12/31/84 1/2/85 RIII **QRK** Kniceley RIII

Med

RIII Krop RIII

Enclosure contains SAFEGUARDS INFORMATION Upon separation this page is Decontrolled

SAFEGUARDS INFORMATION