



BOSTON EDISON

Pilgrim Nuclear Power Station
Rocky Hill Road
Plymouth, Massachusetts 02360

NRCB 92-01

E. Thomas Boulette, PhD
Vice President Nuclear Operations
and Station Director

July 10, 1992
BECO 92-075

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

License DPR-35
Docket 50-293

Response to NRC Bulletin 92-01:
"Failure of Thermo-Lag 330 Fire Barrier
System to Maintain Cabling in Wide Cable Trays and
Small Conduits Free from Fire Damage"

Bulletin 92-01 does not apply to Pilgrim Nuclear Power Station since Thermo-Lag 330 is not installed at PNPS. Prior to the issuance of Bulletin 92-01, and in response to the Information Notices listed in the bulletin, IN 91-47 and IN 91-79, a review of station records was conducted and confirmed Thermo-Lag 330 is not installed.

E. T. Boulette
E. T. Boulette

cc: See Page 2

Commonwealth of Massachusetts)
County of Plymouth)

Then personally appeared before me, E. T. Boulette, who being duly sworn, did state that he is Vice President - Nuclear Operations/Station Director of Boston Edison Company and that he is duly authorized to execute and file the submittal contained herein in the name and on behalf of Boston Edison Company and that the statements in said submittal are true to the best of his knowledge and belief.

My commission expires: October 5, 1995
DATE

Peter M. Kahler
NOTARY PUBLIC

9207240174 920710
PDR ADCK 05000293
Q PDR

240710

JEHA 1/0

BOSTON EDISON COMPANY

U.S. Nuclear Regulatory Commission

Page 2

cc: Mr. R. Eaton, Project Manager
Division of Reactor Projects - 1/II
Office of Nuclear Reactor Regulation
Mail Stop: 14D1
U. S. Nuclear Regulatory Commission
1 White Flint North
11555 Rockville Pike
Rockville, MD 20852

U. S. Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, PA 19406

Senior NRC Resident Inspector
Pilgrim Nuclear Power Station

GGW/cab/BUL9201