


January 19, 1984

Note to Al Schwencer

SUBJECT: LASALLE - FAST STARTS ON DIESEL GENERATORS (OELD # 841 060)

This prenotice on LaSalle will handle the problem quite well. However, I want to raise a second question. The tech spec in LaSalle 2 is written wrong. When are we going to get around to fixing it? It now prohibits fast starts. That is not a good idea and not what we ought to do. We ought to simply not require them. But answering my question should not hold up getting this notice out into the Register.



Joe Scinto

8502090060 840518
PDR FOIA
ADAT084-166 PDR

137