

RECEIVED
NRC

1985 FEB 14 AM 10 58

REGION V PDR

FEBRUARY 12, 1985

U. S. NUCLEAR REGULATORY COMMISSION
REGION V SUITE 210
1450 MARIA LANE
WALNUT CREEK, CALIFORNIA 94596

ATTENTION: J. B. MARTIN,
REGIONAL ADMINISTRATOR

REFERENCE: HEXCEL/MCI REPORT TO YOUR OFFICE
DATED JANUARY 23, 1985

DEAR SIR,

ATTACHMENT CI OF THIS REPORT SHOULD BE REPLACED WITH
TR-527 REV. B, ENCLOSED.

RESPECTFULLY,


HAROLD GRAPER

HG:MO

8503040480 850212
PDR ADOCK 05000373
S PDR

LE19 Change: Inpo
LPOR
NRC PDR
NSIC Silver } Ltr
Only

10 CFR 2.790 INFORMATION

10 CFR 2.790 INFORMATION

Log Sheet No. 51

PART 21 REPORT LOG SHEET

- 1. Subject of Report - Energy absorbing Pipe Restraints

- 2. Date Verbal Notification Received - Received By -

- 3. Date Information Placed in Daily Report - - - -

- 4. Name and Address of Person Providing Verbal Notification 1 -
 - a) Name -
 - b) Company and Address -
 - c) Telephone No. -

- 5. Description of Problem - Energy absorbing pipe restraints were found to have dynamic crush strength values below acceptable levels.

- 6. Nuclear Facilities Affected - BRYAN, BRAIDWOOD AND LASALLE PLANTS.

- 7. Date 5-day Written Report Due - Date Received - 11/13/84

- 8. Div. Secretary Mail Written Report to HQ's and Other Affected Regions
 - a) Date Mailed to HQ's Document Control Desk -
 - b) Date Mailed to Other Regions - III

- 9. Generic Issue Data Sheet (TI-2500/3) submitted? Yes No

- 10. Additional Comments - ~~FACT TO R~~ ON 11/16/84

Part 21 Report Screened by T. Young Jr.
 Cognizant Section Chief: T. Young Jr.

Date 11/21/84
 Date 11/21/84

Region V Form No. 809
 Revised 3/13/84

10 CFR 2.790 INFORMATION

10 CFR 2.790 INFORMATION

Attachment 1

IE-19