

ENCLOSURE 1

NOTICE OF VIOLATION

South Carolina Electric and Gas Company
V. C. Summer

Docket No. 50-395
License No. NPF-12

The following violation was identified during an inspection conducted on November 26 - December 1, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification 3.7.10 requires all penetration fire barriers protecting safety-related areas to be functional at all times. With one or more of the penetration fire barriers nonfunctional, a continuous fire watch is required to be established on at least one side of the affected penetration within one hour. Fire doors in fire barriers are penetration fire barriers and must be maintained functional or a fire watch established.

Contrary to the above, fire door CB-401 for fire penetration between the cable spreading area and stairwell was found at 1:15 a.m., on November 29, 1984, to be nonfunctional and a fire watch had not been established.

This is a Severity Level IV violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: DEC 19 1984

8503050586 850201
PDR ADDCK 05000395
PDR
G