from the desk of

Bill Raymond

Recieved JS Stewart

10/24/90

FOR Don Haverkamp Scott Stewart R1-90-4-120, ISSUE 9

SUBJECT: RECEIPT OF INFORMATION ON MILLSTONE 3 FUEL OIL

residents reviewed our office and personal files. No information on the Millstone 3 fuel oil sampling issue was located. Further, none of the residents recalled receiving such information.

The memo(s) on Millstone 3 fuel oil you sent to us (attached) was routed to all residents to see if anyone recognized the documents. Again, no one recalls having seen the material before at the Millstone resident office.

ken kolaczyk thinks he did see some of the writeups during one of his inspections in the NSE or QAD area onsite while performing an inspection of the NU assessment functions. He recalls, at that time, he felt the issue was being adequately addressed. I am returning the subject information for your information and files.

Based on the above. I have concluded that the materials were never received at the resident office.

My impression of this matter is that, if merely a copy of the enclosures was transmitted to the NRC office without explanation or statement of a concern, then the individual chose a rather poor way to bring a matter to NRC attention for action.

KB6

## SAMPLE RECORD OF ALLEGATION PANEL DECISIONS

SITE: 12,34 HOSSAM NECK P	ANEL ATTENDEES:
ALLEGATION NO .: P1-90-4-17-0 C	hairman - Wiggins
DATE: 11/21/90 (Ktg. 1 23 4 5) B	ranch Chief - Fcw
PRIORITY: High Medium Low 5	ection Chief (AOC) - Stewart
SAFETY SIGNIFICANCE: Yes No Unknown O	thers - Gray - Rriggs - DRS mgm
CONCURRENCE TO CLOSEOUT: DD BC SC	Woodard - DRS inspector
CONFIDENTIALITY GRANTED: Yes No - (See Allegation Receipt Report)	
IS THEIR A DOL FINDING: Yes No	
IS CHILLING EFFECT LETTER WARRANTED: Yes	No
HAS CHILLING EFFECT LETTER BEEN SENT: Yes	No
HAS LICENSEE RESPONDED TO CHILLING EFFECT L	ETTER: Yes No
ACTION:	
1) Issue 9 - Document to Rile	4 CONSIDER CLOSER COL
w/otanina)	
2) Issue 6 - Pertam internal	review or IREF resumme to determine
It time table was contrar to p	
3) Consider technical issue w/	DRS inspection (Woodard), 1/23
Tesmo 6 - Butine closeout	
4)	
5)	
NOTES:	