UNITED STATES

NUCLEAR TIEGULATORY COMMISSION

REGION!Y

611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

SEP 8 1992

Docket No. 030-05933
License No. 35-11114-01

Capital X-Ray Services, Inc. ATTN: George Johnson Radiation Safety Officer 2133 South 49th West Avenue Tulsa, Oklahoma 74107

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 030-05933/92-01

The refers to the routine, unannounced inspection conducted by Mr. Mark R. Shaffer of this office on August 25, 1992. The inspection included a review of activities authorized by Byproduct Material License No. 35-11114-01. At the conclusion of the inspection, the findings were discussed with members of your staff.

The inspection was an examination of activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observation of activities in progress.

No violations or deviations were identified; therefore, no response to this letter is required.

The inspector observed that the licensee possessed ten radiographic exposure devices containing iridium-192 and three devices containing cobalt-60 to perform industrial radiography at temporary job sites throughout the state of Oklahoma. Licensed activities were also performed within a fixed radiographic exposure vault located at the licensee's permanent storage facility in Tulsa. The inspector noted that records of licensed activities were well maintained and adequate for the size and scope of the radiation safety program.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter will be placed in the NRC Public Document Room.

9209140025 920908 REG4 LIC30 35-11114-01 PDR

1507

Should you have any questions concerning this letter, please contact the inspector identified above at (817) 860-8100.

Sincerely,

Chaly L. Cary

Charles L. Cain, Chief Nuclear Materials Inspection Section

cc: Oklahoma Radiation Control Program Director

bcc: DMB - Original (IE-07) JLMilhoan LJCallan JPJaudon MRodriguez, OC/LFDCB (4503) *WLFisher *CLCain *MRShaffer *NMIS *MIS System *RIV Files (2) *RSTS Operator *REHall, URFO

*W/IFS Form

RIV: NMISYNE	C:NMISONS	
MRShaffer	CLCain	
09/3/92	09/3/92	

bcc: DMB - Original (IE-07) JLMilhoan LJCallan JPJaudon MRodriguez, OC/LFDCB (4503) *WLFisher *CLCain *MRShaffer *NMIS *MIS System *RIV Files (2) *RSTS Operator *REHall, URFO

*W/IFS Form

RIV: NMISSAC	C:NMISCND	
MRShaffer	CLCain	
09/3/92	09/3/92	