BOARD

William M. Wilson, Chairman J. Lorin Mason, Jr., M.D., Vice-Chairman Leonard W. Douglas, M.D., Secretary Moses H. Clarkson, Jr. George G. Graham, D.D.S. Barbara P. Nuessle

> COMMISSIONER Robert S. Jackson, M.D. 2600 Bull Street Columbia, S.C. 29201

50-413/414

October 2, 1981

Mr. John Lehr Environmental Engineering Branch, AR-5200 U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Re: Duke Power - Catawba Nuclear Station York County

Dear John:

th Carolina

menta

nentof

Regarding our meeting of September 24, 1981, and the discussion concerning the above referenced facility, the following comments may be of some benefit:

- -no biological or physical studies were done on Lake Wylie nor will any be required by this Department.
- --SC DHEC has only one monitoring station on the northern part of Lake Wylie with minimal data collection capabilities.
- --Cooling tower blowdown must be discharged from the "cool" side of the tower; no immediate plans for thermal plume studies on this discharge (may require thermal plume study later).
- -all housing, except the larger sub-divisions, have septic tanks system.
- -enclosed is a memo from our Enforcement Division in regards to the aqua-culture system.

If any additional information is needed, please feel free to call.

Sincerely,

nal lacorte

Brad Peacock, Engineer Industrial & Agricultural Wastewater Division Bureau of Wastewater & Stream Quality Control

PDR

8307070053 811002 PDR ADOCK 05000413

Add 5. Adensam Add 5. Adensam K. Jabbour R. Bullard R. Bullard

BP/jf

South Carolina Department of Health and Environmental Control

SEP 25 1981

INDUSTRIAL & AGRICULIURAL WASTEWATER DIVISION September 25, 1981

BOARD William M. Wilson, Chairman J. Lorin Mason, Jr., M.D., Vice-Chairman Leonard W. Douglas, M.D., Secretary Oren L. Brady, Jr. Moses H. Clarkson, Jr. Gerald A. Kaynard Barbara P. Nuessle

> COMMISSIONER Robert S. Jackson, M.D. 2600 Bull Street Columbia, S.C. 29201

MEMORANDUM:

TO: Brad Peacock Industrial Engineering

FROM:

Dale Farence Mal

Enforcement Section

SUBJECT: NPDES Permit effluent violation at Duke Power/Catawba Nuclear Station.

During March thru June 1981, the referenced facility's discharge monitoring reports indicated violations of the total suspended solids (TSS) and biological oxygen demand (BOD) parameter limits. Duke Powers' accompanying letter explained that the facility had been experiencieng problems due to algae growth, and that an in-house investigation had already been initiated to correct the violations.

On the basis of Duke's explanation, enforcement action was temporarily withheld. Upon receipt of the facility's next quarterly discharge monitoring report, the situation will be reviewed by the enforcemen section. If TSS and BOD violations still exist, a conference will be scheduled with Duke representatives to discuss the violations. At that time, the possible issuance of an Order requiring correction of these violations will be considered.

DRF/ik