



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

*BR*

MAY 24 1984

MEMORANDUM FOR: George Knighton, Chief, Licensing Branch #3, DL  
FROM: Faust Rosa, Chief, Instrumentation and Control Systems Branch,  
DSI  
SUBJECT: INPUT TO SALP REPORT FOR SHEARON HARRIS UNIT 1

Plant Name: Shearon Harris Unit 1  
Docket No.: 50-400  
Licensing Status: OL  
Responsible Branch: LB#3  
Project Manager: B. Buckley  
Review Branch: ICSB  
Review Status: Incomplete

In response to your request by a memorandum dated May 21, 1984, the Instrumentation and Control Systems Branch provides the attached SALP input in accordance with Office Letter No. 44.

*Faust Rosa*

Faust Rosa, Chief  
Instrumentation and Control Systems Branch  
Division of Systems Integration

Enclosure:  
As stated

cc: R. W. Houston  
B. Buckley

CONTACT: H. Li, ICSB  
x29452

*8406010504* *XA*  
*CF*

ICSB SALP INPUT

PLANT: Shearon Harris Unit 1  
SUBJECT: Safety Evaluation Report

EVALUATION CRITERIA	PERFORMANCE CATEGORY	BASIS
1. Management Involvement	N/A	No basis for assessment.
2. Approach to Resolution of Technical Issues	1	A clear understanding of the issues was demonstrated. A technically sound and thorough approach was used to effect a timely resolution.
3. Responsiveness	1	Technically sound and thorough responses to NRC initiatives were made to effect a timely resolution.
4. Enforcement History	N/A	No basis for assessment.
5. Reportable Events	N/A	No basis for assessment.
6. Staffing	2	Adequate technical staffs have participated in review meetings to effect a timely resolution of open items.
7. Training	N/A	No basis for assessment.