SAFEGUARDS INFORMATION



UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II 101 MARIETTA STREET, N.W. ATLANTA, GEORGIA 30323

Report Nos.: 50-280/92-19 and 50-281/92-19

Licensee: Virginia Electric and Power Company

Glen Allen, VA 23060

Docket Nos.: 50-280 and 50-281 License Nos.: DPR-32 and DPR-37

Facility Name: Surry 1 and 2

Inspection Conducted: August 31 - September 4, 1992

Tobin, Senior Safeguards Inspector Date Signed

Approved by: A

D. R. McGuire, Chief Safeguards Section

Nuclear Material Safety and Safeguards Branch Division of Radiation Safety and Safeguards

SUMMARX

Scope:

This routine, unannounced inspection was conducted in 'he area of the Physical Security Frogram for Power Reactors. Specifically, the inspector reviewed Plans, Audits, Barriers, Alarms, Alarm Stations, Communication, Testing, Compensatory Measures, and Power Supplies.

Results:

In the area inspected, violations or deviations were not identified.

The licensee continues to have strong support of its security programs, audits were a strength, as was the maintenance of security equipment. Barriers, detectors, alarm stations, and communications were adequate. Power supplies are tested and reliable. The licensee was encouraged to complete its extensive review of the commitments found in the security plan to verify the validity of each commitment (see Paragraph 2.a for details).

9209280011 92092 PDR ADDCK 05000

SAFEGUARDS INFORMATION

Document transmitted his loss! contains sensitive unclassified information. When requested fines enthrines, the document is secondaries.