



**Commonwealth Edison**

One First National Plaza, Chicago, Illinois  
Address Reply to: Post Office Box 767  
Chicago, Illinois 60690

DMB

October 16, 1984

Mr. James G. Keppler  
Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Subject: Byron Station Units 1 and 2  
Braidwood Station Units 1 and 2  
Final Response to IE Bulletin 80-23  
"Failure of Solenoid Valves Manufactured  
by Valcor Engineering Corporation"  
NRC Docket Nos. 50-454/455/456/457

References (a): IE Bulletin 80-23 dated 11-14-80

(b): E. D. Swartz letter to J. G. Keppler  
dated June 17, 1981

Dear Mr. Keppler:

Reference (a) requested that the Commonwealth Edison Company provide a written report regarding our plans to replace or repair the potentially defective valves and a tentative schedule. Reference (b) provided this information. Because our file does not contain a notice of completion to the NRC, we are issuing this letter to advise you that all corrective actions were completed for the identified valves at Byron and Braidwood Stations.

To the best of my knowledge and belief the statements contained above are true and correct. In some respects these statements are not based on my personal knowledge but upon information furnished by other Commonwealth Edison employees, consultants, and contractors. Such information has been reviewed in accordance with Company practice and I believe it to be reliable.

Please address any questions that you or your staff may have concerning our response to this office.

Respectfully,

G. L. Alexander  
Nuclear Licensing Administrator

cc: RIII Inspector - BY/BW

9321N

8410260023 841016  
PDR ADDCK 05000454  
Q PDR

OCT 22 1984

IE 11 40