UNITED STATES

## NUCLEAR REGULATORY COMMISSION

REGIONIV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

OCT - 6 1990

Dockets: 50-445

50-446

150 se: NPF-87

Construction Permit: CPPR-127

7U Electric

ATIN: W. J. Cahill, Jr., Group Vice President

Nuclear Engineering and Operations Skyway Tower

400 North Olive Street, L.B. 81

Dallas, Texas 75201

Gentlemen:

SUBJECT: NRC INSPECTION REPORT 50-445/92-33; 50-446/92-33

(NOTICE OF VIOLATION)

This refers to the inspection conducted by Messrs. R. B. Vickrey and C. J. Paulk of this office on September 8-10, 1992. The inspection included a review of activities authorized for your Comanche Peak Steam Electric Station facility. At the conclusion of the inspection, the findings were discussed with you and those members of your staff identified in the enclosed report. At that exit meeting, the inspectors identified an unresolved item relating to the identification of deficiencies on Unit 2 safety-related instrument transmitters. On September 30, 1992, a followup exit was conducted via telephone with Mr. R. Walker and other members of your staff and they were informed that we had concluded that a violation had occurred regarding a failure to properly implement procedures related to corrective action.

Areas examined during the inspection are identified in the report. These included instrument component and system procedure review, work observation, and record reviews related to installed instrumentation at Comanche Peak Steam Electric Station, Unit 2.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violation is of concern because the failure to follow the procedures for identifying deficiencies on Unit 2 could have an impact on the safe operation of Unit 1.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future

9210130049 921006 ADDCK 05000445 PDR

16019

inspections the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

The responses directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96.511.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

Should you have any questions concerring this inspection, we will be pleased to discress them with you.

Sincerely,

A. Bill Beach, Director Division of Reactor Projects

Enclosures:

1. Appendix A - Notice of Violation

2. Appendix B - NRC Inspection 50-445/92-33 w/Attachment 50-446/92-33 w/Attachment

cc w/enclosures:

TU Electric

ATTN: Roger D. Walker, Manager of Regulatory Affairs for Nuclear Engineering Organization

Skyway Tower 400 North Olive Street, L.B. 81 Dallas, Texas 75201

Juanita Ellis President - CASE 1426 South Polk Street Dallas, Texas 75224

GDS Associates, Inc. Suite 720 1850 Parkway Place Marietta, Georgia 30067-8237

1U Electric Bethesda Licensing 3 Metro Center, Suite 610 Bethesda, Maryland 20814

Jorden, Schulte, and Burchette ATTN: William A. Burchette, Esq. Counsel for Tex-La Electric Cooperative of Texas 1025 Thomas Jeffirson St., N.W. Washington, D.C. 20007

Newman & Holtzinger, P.C. ATTN: Jack R. Newman, Esq. 1615 L. Ctreet, N.W. Suite 1000 Washington, D.C. 20036

Texas Department of Labor & Standards ATTN: G. R. Bynog, Program Manager/ Chief Inspector Boiler Division P.O. Box 12157, Capitol Station Austin, Texas 78711

Honorable Dale McPherson County Judga P.O. Box 851 Glen Rose, Texas 76043

Texas Radiation Control Program Director 1100 West 49th Street Austin, Texas 78756

Owen L. Thero, President Quality Technology Company Lakeview Mobile Home Park, Lot 35 4793 E. Loop 820 South Fort Korth, Texas 76119 TU Electric

bcc to DMB (IEO1) - DRS

bcc distrib. by RIV:

J. L. Milhoan DRP Lisa Shea, RM/ALF, MS: MNBB 4503 DRSS-FIPS Project Engineer (DRP/B) DRS

C. Paulk B. Vickrey T. Westerman Resident Inspector (2)
Section Chief (DRP/B)
MIS System
RSTS Operator
RIV File
Chief, Technical Support Section

RIV:	RI:PSS	RI:PSS		D: DRS	D: PRP
RBVi	ckrey W	CJPaulk &	TFWesterman	Sucollins for	ABBeach
9/30		9/30/92	10/1/92	10 15 192	10/6/92

bcc to DMB (IEO1) - DRS bcc distrib. by RIV:

J. L. Milhoan
DRP
Lisa Shea, RM/ALF, MS: MNBB 4503
DRSS-TIPS
Project Engineer (DRP/B)
DRS
C. Paulk
B. Vickrey
T. Westerman

Resident Inspector (2)
Section Chief (DRP/B)
MIS System
RSTS Operator
RIV File
Chief, Technical Support Section

RIV:RI:PSS	RI:PSS	C:PSS	D: DRS 200	D: PRP
RBVickrey (4)	CJPaulk &	TFWesterman	SJCollins for	ABBeach
9 /30/92	9/30/92	10/1/92	10 15 192	10/6/92