

Doc

OCT 9 1992

Docket No. 50-346

Centerior Service Company
ATTN: Mr. Donald Shelton
Vice President
Nuclear - Davis-Besse
c/o Toledo Edison Company
300 Madison Avenue
Toledo, OH 43652
Dear Mr. Shelton:

This refers to the routine safety inspection conducted by Mr. R. A. Paul of this office on September 21 - 25, 1992, of activities for your Davis-Besse Nuclear Power Station. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations of activities in progress.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

M. C. Schumacher
M. C. Schumacher, Chief
Radiological Controls Section 1

Enclosure: Inspection Report
No. 50-346/92015(DRSS)

See Attached Distribution:

RIII *JP* Paul/jp RIII *Jackiw* Jackiw RIII *MS* Schumacher

IF 06 11

9210190047 921009
PDR ADOCK 05000346
G PDR

Centerior Service Company

2

OCT 5 1992

Distribution:

cc w/enclosure:

L. Storz, Plant Manager

DOD/DCB (RIDS)

OC/LFDCB

Resident Inspector, RIII

James R. Williams, State of Ohio

Robert E. Owen, Ohio

Department of Health

A. Grandjean, State of Ohio,

Public Utilities Commission