Docket No. 50-346

Dear Mr. Shelton:

This refers to the inspection conducted by Mr. Joseph M. Ulie ard others of this office on January 29-30, May 29, July 12 and 29. November 18-19, 1991, and October 6, 1992. The inspection included a review of authorized activities for your Davis-Besse Nuclear Power Station. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

During this inspection we followed up on matters that were discussed in Inspection Report No. 50-346/90007, which was mailed to you on August 22, 1990. Aspects of that inspection were referred to our Office of Investigations. A synopsis of the ensuing investigation is provided in the enclosure to the inspection report.

As a result of our involvement in the investigation, we concluded that you had a significant weakness with integrating operations and angineering functions in the review and validation of complex procedures. Had the NRC not brought this to your attention, during certain conditions unknown to you, a self-induced station blackout could have occurred while you were responding to a serious control room fire. In order co develop a level of confidence that the above noted weakness has not produced sequencing problems in other procedures, we request you consider reviewing a sample of procedures with time dependent actions which could create unanticipated operational problems if the procedural steps were not completed in the proper sequence. Please provide our office with the results of any such review that you may undertake.

Certain other activities, set forth in the enclosure to this letter, appear to be a deviation from commitments that you have made in previous correspondence with the Commission. A written response is not required.

9211100108 921103 PDR ADDCK 05000346 0 PDR

1501 1

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosures will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

original signed by

H. J. Miller, Director Division of Reactor Safety

## Enclosures:

1. Notice of Deviation

2. Inspection Report

No. 50-346/92016(DRS)

Synopsis of OI Report No. 3-90-016

cc w/enclosures: L. Storz, Plant Manager DCD/DCB (RIDS) OC/LFDCB

Resident Inspector, RIII J. B. Hopkins, LPM, NRR

State Liaison Officer, State of Ohio

Robert E. Owen, Ohio Department of Health

A. Grandjean, State of Ohio, Por lic Utilities Commission

RIJI. 142 Ulie/sd/jk 11/03/92

RIII Ring 11/3/92

RIII TOR Reidinger 11/3/92

RIII ONA Martin 11/3/92 Jablonski

11/5/92 RIII ( see previous concurrence ) DeFayette Pawlik

11/ /92

RIII PO-1-

Jackiwladabay 11/3/92

RIII REIL 11

Miller 11/ /92 11/5/92 We will gladly discuss any questions you have concerning this inspection. Sincerely,

H. J. Miller, Director Division of Reactor Safety

Enc'ast e...

1. Notice of Deviation

 Inspection Report Na. 50-346/92016(DRS)

3. Synopsis of OI Report No. 3-90-016

cc w/enclosure:
L. Storz, Plant Manager
DCD/DCB (RIDS)
OC/LFDCB
Resident Inspector, RIII
State Liaison Officer, State
of Ohio
Robert E. Owen, Ohio
Department of Health
A. Grandjean, State of Ohio,

RIII RIII Wlie/sd Reddinger Jablonski y Ringus Martis

RHI RWO RIII DeFayette Pawlik Miller 10/30/92