

Indian Point 3
Nuclear Power Plant
P.O. Box 215
Buchanan, New York 10511
914 739.8200



October 15, 1984
IP-WDH-3599

Mr. Thomas T. Martin
Division of Engineering and Technical Programs
U.S. Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

SUBJECT: IE Bulletin No. 84-02: "Failures of General Electric
Type HFA Relays in Use in Class 1E Safety Systems"

REFERENCE: Letter from John C. Brons to Thomas T. Martin,
dated July 17, 1984

Dear Mr. Martin:


Per the referenced letter, the Authority submitted its response to the specific concerns of the subject bulletin. Whereas the specific bulletin concerns do not apply to IP-3, a review of the general concerns for applicability to IP-3 was requested.

As indicated in the referenced letter, the Authority is ascertaining to what extent, if any, the general concerns cited in IE Bulletin No. 84-02 may apply to IP-3. To date, a detailed and comprehensive relay data base has been established. The Authority, however, is still in the process of obtaining the remaining information necessary to commence evaluation of the established data base.

Upon completion of these evaluations, the Authority will provide the information necessary to close-out this bulletin.

Should you or your staff have any questions regarding this matter, please contact Mr. W. Hamlin of my staff.

Very truly yours,


John C. Brons
Resident Manager

8410300271 841015
PDR ADDOCK 05000286
Q PDR

cc: Resident Inspector's Office

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

TEL
/o