

FEB 07 1985

Docket No. 50-334

Duquesne Light Company
ATTN: Mr. J. J. Carey
Vice President
Nuclear Group
Post Office Box 4
Shippingport, Pennsylvania 15077

Gentlemen:

Subject: Inspection No. 50-334/84-23

This refers to the routine safety inspection conducted by Mr. F. Paulitz of this office on October 9-12, 1984, at Beaver Valley Power Station, Unit 1, of activities authorized by NRC License No. DPR-66 and to the discussions of our findings held by Mr. F. Paulitz with Mr. T. O. Dowhy at the conclusion of the inspection.

Areas examined during this inspection are described in the NRC Region I Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no violations were observed.

No reply to this letter is required. Your cooperation with us in this matter is appreciated.

Sincerely,

Original Signed By:

S. Ebnetter

fo Stewart D. Ebnetter, Director
Division of Reactor Safety

Enclosure:
NRC Region I Inspection Report No. 50-334/84-23

8502150122 850207
PDR ADOCK 05000334
Q PDR

OFFICIAL RECORD COPY

DL50-334/84-23 - 0001.0.0
01/30/85

IE01
1/1

FEB 07 1985

cc w/encl:

F. Bissert, Manager, Nuclear Support Services
C. E. Ewing, QA Manager
W. S. Lacey, Station Superintendent
R. Druga, Chief Engineer
R. Martin, Nuclear Engineer
J. Sieber, Manager, Nuclear Safety and Licensing
T. D. Jones, Manager, Nuclear Operations
R. M. Mafrice, Nuclear Engineer
N. R. Tonet, Manager, Nuclear Engineering
M. Coppula, Superintendent of Technical Services
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
Commonwealth of Pennsylvania

bcc w/encl:

Region I Docket Room (with concurrences)
Senior Operations Officer (w/o encls)
Section Chief, DPRP

RI:DRS *JP*
Paulitz/sm
1/30/85

JAC
RI:DRS
Anderson
1/30/85

JE
RI:DRS
Ebnetter
JE/85

OFFICIAL RECORD COPY

DL50-334/84-23 - 0002.1.0
01/30/85