



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

February 6, 1985

Director
Office of Nuclear Reactor Regulation
U S Nuclear Regulatory Commission
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket Nos. 50-282 License Nos. DPR-42
50-306 DPR-60


Steam Generator Tube Plugging

In accordance with Technical Specification 4.12.E.1, the following steam generator tube plugging information is provided for the information of the NRC Staff.

Following the recent inservice inspection of the Unit 1 steam generators, sixteen tubes were plugged. Seven tubes were plugged in steam generator 11 and nine in steam generator 12. The percentage of tubes plugged is 1.5% and 0.8% in steam generators 11 and 12, respectively.

This information will be expanded upon in the Inservice Inspection Report for each unit. Also Tables 4.3-13 and 14 of the Prairie Island Updated Safety Analysis Report will be updated in the next revision.

If you have any questions concerning this information please call.


David Musolf
Manager - Nuclear Support Services

DMM/EFE/dab

c: Regional Administrator-III, NRC
NRR Project Manager, NRC
Resident Inspector, NRC
G Charnoff

8502150160 850206
PDR ADDOCK 05000282
G PDR

A-001
1/0