

September 7, 1973

Jaraey Central Power & Light Company ALIS: Mr. I. R. Finfrock, Jr. Vice President - Generation Maison Avenue at Punch Bowl Road Marristown, New Jersey 07960

Gentlemen:

This confirms our telephone call to Mr. J. Carrol, Oyster Creek Plant Superintendent, on September 6, 1973, pertaining to the possibility of inverted absorber tubes in the control rods at the Oyster Creek Nuclear Generating Station. It was agreed that during your outage in early September, that is planned for hydraulic snubber inspections, you would conduct shutdown margin tests on all control rods to verify that the minimum shutdown margin is at least 0.0075 \(\Delta k/k\) at cold, xenon-free, operating samarium conditions. It is expected that these tests will be performed at approximately 120°F and allowance will be made for the shutdown worths of xenon and samarium.

Provide this office with a written report of the results within 10 days of the completion of the tests. If any anomaly should be found, report in accordance with the Technical Specifications for Oyster Creek.

Sincerely,

Donald J. Skovholt Assistant Director for

Operating Reactors

Directorate of Licensing

cr: see next page

Show, Pittman, Potts, Trowbridge
E Madlen
910 - 17th Street, N. W.
Washington, D. C. 20006

GPU Service Corporation
ATTN: Mr. Thomas M. Crimmins
Safety & Licensing Manager
260 Cherry Hill Road
Parsippany, New Jersey 07054

J. Lester Yoder, Jr., Esquire 206 Horner Street Toms River, New Jersey 08753

Mr. Kenneth B. Walton Brigantine Tutoring 309 - 21st Street, South Brigantine, New Jersey 08203

Miss Dorothy R. Horner Township Clerk Township of Ocean Waretown, New Jersey 08753

Ocean County Library 15 Hooper Avenue Toms River, New Jersey 03753