

JUN 12 1973

H. D. Thornburg, Chief, Field Support & Enforcement Branch
Directorate of Regulatory Operations, HQ

RO INSPECTION REPORT NO. 50-219/73-08
JERSEY CENTRAL POWER & LIGHT COMPANY
OYSTER CREEK - BWR

The subject inspection report is forwarded for your information.

The results of the several inspections preceeding this meeting with the President of Jersey Central Power & Light Co. revealed serious problems practically everywhere we looked, most of which reflected negatively on management. Underlying causes apparent to us were candidly and frankly discussed. We believe the message registered. It is now up to the licensee. Management has its work cut out. Few of the corrective actions called for can be accomplished overnight.

A timely followup inspection of management systems is in order. I will be forwarding by separate memorandum my recommendations in this regard for all applicable facilities in Region I, including Oyster Creek.

R. T. Carlson, Chief
Facility Operations Branch

Enclosure:
Subject Inspection Report

cc: RO:HQ (5)
DR Central Files
RO Files
Regulatory Standards (3)
Directorate of Licensing (13)
RO Directors

B/219

OFFICE ▶	RO <i>RC</i>				
SURNAME ▶	Carlson:smg				
DATE ▶	6/12/73				