

UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGIONIV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

APR 1 1 1996

Entergy Operations, Inc. ATTN: C. R. Hutchinson, Vice President Operations - Grand Gulf P.O. Box 756 Port Gibson, Mississippi 39150

SUBJECT: NRC INSPECTION REPORT 50-416/96-02

This refers to the inspection conducted by Mr. T. F. Stetka and Ms. L. J. Smith of this office on January 8 through February 9, 1996, at the Grand Gulf Nuclear Station facility. The purpose of the inspection was to determine whether activities authorized by the license were conducted safely and in accordance with NRC requirements. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress. The purpose of this inspection was to determine the effectiveness of your self assessment of the engineering and corrective action programs.

Your self assessment concluded that you had implemented effective engineering and corrective action programs. Our independent inspection of your self-assessment process confirmed this conclusion. Therefore, in accordance with NRC Inspection Procedure 40501. "Licensee Self assessments Related to Team Inspections," the NRC plans no further inspection effort at the Grand Gulf Nuclear Station for NRC Inspection Procedures 37550 and 40500 during Systematic Assessment of Licensee Performance Cycle 12.

As a result of our inspection effort, we noted that your staff did not plan to inspect or replace the valve stem on the reactor core isolation cooling pump turbine governor during the next outage. This valve stem is susceptible to corrosion and has failed at other Entergy Operations facilities. This indicates an lack of consistency in the application of engineering disciplines among the Entergy Operation facilities. We encourage you to review this condition to ensure continued reliable operation of the reactor core isolation cooling pump turbine.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice." a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

Sincerely.

Thomas P. Gyyng. Director Division of Reactor Safety

Docket: 50-416 License: NPF-29

Enclosure: NRC Inspection Report 50-416/96-02 w/attachment

cc w/enclosure: Entergy Operations, Inc. ATTN: H. W. Keiser, Executive Vice President and Chief Operating Officer P.O. Box 31995 Jackson, Mississippi 39286-1995

Wise, Carter, Child & Caraway ATTN: R. B. McGehee, Esq. P.O. Box 651 Jackson, Mississippi 39205

Winston & Strawn ATTN: Nicholas S. Reynolds, Esq. 1400 L Street. N.W. - 12th Floor Washington, D.C. 20005-3502

Mississippi Department of Natural Resources ATTN: Sam Mabry. Director Division of Solid Waste Management P.O. Box 10385 Jackson, Mississippi 39209

Claiborne County Board of Supervisors ATTN: President Port Gibson. Mississippi 39150

Bechtel Power Corporation ATTN: Mr. K. G. Hess P.O. Box 2166 Houston, Texas 77252-2166 Bechtel Power Corporation ATTN: N. G. Chapman, Manager 9801 Washington Boulevard Gaithersburg, Maryland 20878

Entergy Operations, Inc. ATTN: D. L. Pace. Grand Gulf Nuclear Station General Manager P.O. Box 756 Port Gibson, Mississippi 39150

The Honorable William J. Guste, Jr. Attorney General Department of Justice State of Louisiana P.O. Box 94005 Baton Rouge, Louisiana 70804-9005

Office of the Governor State of Mississippi Jackson, Mississippi 39201

Mike Moore, Attorney General Frank Spencer, Asst. Attorney General State of Mississippi P.O. Box 22947 Jackson, Mississippi 39225

State Board of Health ATTN: Dr. F. E. Thompson, Jr. State Health Officer P.O. Box 1700 Jackson, Mississippi 39205

Division of Radiation Health Mississippi Department of Health ATTN: Eddie S. Fuente, Director State Liaison Officer P.O. Box 1700 Jackson, Mississippi 39215-1700

Entergy Operations. Inc. ATTN: J. G. Dewease, Vice President Operations P.O. Box 31995 Jackson, Mississippi 39286-1995 Entergy Operations, Inc. ATTN: Michael J. Meisner, Director Nuclear Safety and Regulatory Affairs P.O. Box 756 Port Gibson, Mississippi 39150 E-Mail report to D. Nelson (DJN) E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IE01)

bcc distrib. by RIV:

L. J. Callan DRP Director Branch Chief (DRP/D) Project Engineer (DRP/D) Branch Chief (DRP/TSS) Resident NRC inspector DRS-PSB

MIS System RIV File

Leah Tremper (OC/LFDCB, MS: TWFN 9E10)

Willah

E-Mail report to D. Nelson (DJN) E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IEO1)

bcc distrib. by RIV:

L. J. Callan DRP Director Branch Chief (DRP/D) Project Engineer (DRP/D) Branch Chief (DRP/TSS) Resident NRC inspector DRS-PSB MIS System RIV File Leah Tremper (OC/LFDCB, MS: TWFN 9E10)

RIV:SRI:EB	RI:EB	C:EB	D:DRS /	C: PBD; DRSA	DRS N
TFStetka W	LJSmith W	CAVanDendur	gh TPGWIXAN	PHán el	TPGWynpula
4/5/96	4/5/96	4/5/960	4/2/968	4/8/96	4/11/96