



UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION I
970 BROAD STREET
NEWARK, NEW JERSEY 07102

MAY 17 1973

E. M. Howard, Chief, Facilities Construction & Engineering
Support Branch
Directorate of Regulatory Operations, Region I

EVALUATION MEMORANDUM

Mr. Sanders and I conducted an inspection at the Klockner plant in Osnabruck, Germany on April 9 and 10, 1973.

As you would expect, Klockner appears to be guilty of the same practice as KSB and suppliers in the USA of meeting the minimal code requirements and believing this is adequate.

I recommend a continuing audit of Klockner on a twice yearly basis at least, and probably more often if they get the contract for the 24 additional pump casing for SKK.

A handwritten signature in cursive script that reads "Ross L. Brown".

Ross L. Brown
Reactor Inspector

MEMO ROUTE SLIP Form AIC-93 (Rev. May 14, 1947) AEC 1240		See me about this: Note and return	For conc. ce. For signa	For action. For information.
TO (Name and unit) RO Chief, FS&EB RO:HQ (5) DR Central Files Regulatory Standards (3) Directorate of Licensing (13)		INITIALS	REMARKS RO INSPECTION REPORT NO. 50-363/73-01 KLOCKNER WORKS, OSNABRUCK, GERMANY (FORKED RIVER 1)	
		DATE		
TO (Name and unit) RO Directors (4) PDR Local PDF NSIC TIC		INITIALS	REMARKS The subject inspection report is forwarded for information.	
		DATE		
TO (Name and unit) State of New Jersey		INITIALS	REMARKS	
		DATE		
FROM (Name and unit) E. M. Howard, RO:I <i>EMH (m)</i>		REMARKS		
PHONE NO. 3450	DATE 5/18/73			

USE OTHER SIDE FOR ADDITIONAL REMARKS

GPO 1971 O - 447-867

B/236