

In Reply Refer To:
Dockets: 50-445/84-32
50-446/84-11

FEB 15 1985

Texas Utilities Electric Company
ATTN: M. D. Spence, President, TUGCO
Skyway Tower
400 North Olive Street
Lock Box 81
Dallas, Texas 75201

Gentlemen:

This refers to the inspection conducted under the Resident Inspection Program by Mr. H. S. Phillips of this office and NRC contract personnel during the period August 20, 1984, through September 20, 1984, of activities authorized by NRC Construction Permits CPPR-126 and CPPR-127 for the Comanche Peak facility, Units 1 and 2, and to the discussion of our findings with Mr. D. Chapman and other members of your staff at the conclusion of the inspection.

Areas examined during the inspection included a review and evaluation of how effectively Texas Utilities Electric Company management has implemented the corporate quality assurance (QA) program for design, procurement, and construction activities. Special emphasis was placed on evaluating the management of the audit program; management's action to regularly review the status and adequacy of the QA program; and followup on findings pertinent to program management identified by previous NRC and consultant inspection teams. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspectors. These findings are documented in the enclosed inspection report.

During this inspection, it was found that certain of your activities were in violation of NRC requirements. Consequently, you are required to respond to this violation, in writing, in accordance with the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Your response should be based on the specifics contained in the Notice of Violation enclosed with this letter.

These violations may be related to findings identified by the NRC Technical Review Team (TKT). If the issues are considered to be similar, you may respond to the items separately or as part of the Comanche Peak Response Team Action Plan.

RRI *SP*
SPhillips/lt
2/12/84

TL/TF *TH*
DHunnicuttt
2/12/84

D/DRS&S
RBangart
1/184

DL
C/RPB2
DHunter
2/12/84

RM
D/DRS&P
RDenise
2/12/84

NRR *sofa*
Noonan
12/20/84

8502200325 850214
PDR ADOCK 05000445
Q PDR

IEO 1
1/1

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

"Original Signed by:
D. M. HUNNICUTT"

D. R. Hunter, Chief
Reactor Project Branch 2

Enclosure:

1. Appendix A - Notice of Violation
2. Appendix B - NRC Inspection Report
50-445/84-32
50-446/84-11

cc w/enclosure:

Texas Utilities Electric Company
ATTN: B. R. Clements, Vice
President, Nuclear
Skyway Tower
400 North Olive Street
Lock Box 81
Dallas, Texas 75201

Texas Utilities Electric Company
ATTN: J. W. Beck, Manager
Nuclear Services
Skyway Tower
400 North Olive Street
Lock Box 81
Dallas, Texas 75201

bcc to DMB (IE01)

bcc distrib. by RIV:

RPB1
RPB2
EP&RPB
R. Martin, RA
C. Wisner, PAO
R. Denise, DRSP
RIV File
MIS System

RRI-OPS
RRI-CONST.
R. Bangart
J. Gagliardo
D. Hunnicutt
TRT (CPSES) (2)
S. Treby, ELD
D. Eisenhut, NRR

TX State Dept. Health
Juanita Ellis
Renea Hicks
Billie Pirner Garde
S. Phillips